Fugitive Emission Repair Work Order (RWO)

Location Details

Туре	Well Site	LSD/NTS	01-35-017-28W4
Name	EECO FOOTHILLS 1-35-17-28	UWI	100013501728W400
Latitude	50.471553	Longitude	-113.738924



5a7fh426

Screening Details

Date	2023-Jan-02	Screener	Denise Chanson
Method of Detection	Soap Solution		
Screening Notes	<no notes=""></no>		

Emission Details

Main Component	Connector	Sub-Component	Grease Injector	
Repair Rec.	Tighten/Reseal Connection	Recommended Urgency	Repair Within 30 Days	
Description	Grease injection niple is venting gas to atm, downstream side			
Emission Notes	Appears to be loose and not b	roken		



Repair Details

•			
Repaired By*	Date*		
Method of Repair*	Method of Confirming Repair*		
Repair Notes		Cost (w/o tax)	